Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or	U3222	OS Map		91
BOAT Number		Grid References	From	735 206
Total length	0.31		To	733 204
Length unsurfaced	0.31	Location		Hilton

CCC Classification	Route with significant use requiring significant monitoring/managment	
(Tick recommendation)	Route with moderate use requiring some monitoring/managment	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends	

Surveyor	Steve Pighills	Organization or interest	TRF
Date	10/11/16		

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	50%
	Crushed stone	50%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.)	Good

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)	None

Considerations for use and sensitivity re ecological issues, farming issues, other	None

General description of route, and observations		Signed from main highway	No
		Signed both ends	
From Cross Keys corner at south end of Hilton, short lane to T junction after barns. Turn left at finger posts to go back into village		Access from main - easy	Yes
		Highway - awkward	
		Route - through	Yes
		- dead end	
		Fords or water crossings	
		Gradient - generally flat	Yes
		- generally undulating	
		- has steep hills	

Should normally be passable by	2 wheel drive	No	Quad	Yes
	4 wheel drive	No	Trail bike	Yes
	Carriage	No		
	Approx. width at narrowest		12ft	

Recommend one way use due to steepness, narrowness, other condition, state reason		4 wheels	
		2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe	
	No			