



Troutbeck Bridge

Flood Investigation Report



Bell Beck, looking downstream towards Troutbeck Bridge, January 2016

Flood Event 5-6th December 2015

This flood investigation report has been produced by the Environment Agency as a key Risk Management Authority under Section 19 of the Flood and Water Management Act 2010 in partnership with Cumbria County Council as Lead Local Flood Authority.



Version	Prepared by	Reviewed by	Approved by	Date
Draft v1.0	Himz Mistry, CH2M Hill	Jonathan Coates, EA Elizabeth Kelly, EA	Dan Bond, EA	12 th July 2016

Contents

Executive Summary	5
Flooding History	7
Event background	8
Flooding Incident	8
Current Flood Risk Management & Existing Defences	12
Investigation	15
Rainfall Event	15
Sources of Flooding, Flood Flow Routes and Event Timeline	18
Likely Causes of Flooding	19
Environment Agency Flood Incident Response	25
Pre-event Warning and Preparation	25
Post-event Repairs and Maintenance	25
On-going Maintenance Activities	25
Recommended Actions	
Next Steps	28
Appendices	29
Appendix 1: Glossary	29
Appendix 2: Summary of Relevant Legislation and Flood Risk Management Authorities	30
Appendix 3: Links to Other Information on Flooding	32
Appendix 4: Flood Warnings and Alerts	33
Appendix 5: CH2M Hill LIK Projects and Flood Pick Management brochure	3/

Executive Summary

Troutbeck Bridge experienced flooding on three separate occasions in December 2015. These events occurred on the 5th, 6th and 22nd December, and affected several properties in the area. The initial event on 5th December was the most significant of the three events, and was the result of the effects of Storm Desmond. This storm caused a period of prolonged, intense rainfall across Northern England, falling on already saturated catchments, and led to high river levels and flooding in Troutbeck Bridge and beyond.

In response to the flood event, this *Flood Investigation Report* has been completed by the Environment Agency as a key Risk Management Authority (RMA) working in partnership with Cumbria County Council as the Lead Local Flood Authority, under the duties as set out in Section 19 of the Flood and Water Management Act 2010. This report provides details on the flooding that occurred in Troutbeck Bridge on the 5th and 6th of December, and has used a range of data collected from affected residents, site visits, surveys of the area, data collected by observers, as well as river and rainfall telemetry during the flood events.

There are no formal flood defences within Troutbeck Bridge, however the Environment Agency inspect and, if required, subsequently remove gravel from the Bell Beck culvert following flood events. The Environment Agency also clear the trash screen at the inlet to the Bell Beck culvert, situated in a field upstream of Brook Street, to minimise the risk of potential blockages, on receipt of forecast heavy rainfall as a 'high priority' site. Following the extreme rainfall and subsequent flooding in December 2015, gravel removal took place within the Bell Beck culvert, and an estimated 30 tonnes of material was removed. There is an overflow arrangement within the Bell Beck culvert downstream of Calgarth View on the A591, which provides additional culvert capacity to alleviate some of the flooding.

The 5th December flood event affected seven properties directly. This was largely due to issues on Bell Beck, where gravel and stone mobilised from erosion in the open channel upstream of the culvert inlet had washed downstream to reduce the capacity of the Bell Beck culvert, which could not cope with the significant volume of water flowing towards Troutbeck Bridge during the storm. In addition, there were also flooding impacts from surface water runoff, in particular flowing down Sun Lane and the A591 towards Calgarth View and Broadfield. There were also reported impacts from local ordinary watercourses and from the local sewer system overflowing.

This report details the flooding that occurred from these various sources. It identifies the flow routes and the causes of the flooding within Troutbeck Bridge.

Actions have been recommended in this report to manage future flood risk, which will require the involvement of a number of organisations and local communities.

In response to the flooding, a number of community meetings have taken place, and these will continue in order to ensure that all those affected are given the opportunity to be involved in reducing the flood risk in their local area.

Any additional information that residents and others can provide to the Environment Agency and Cumbria County Council to help develop our understanding of the flooding is welcomed. A lot of information has already been provided, much of which has been used to inform this report. The scale of this report means that not every piece of

information can be incorporated into the document. Any additional information should be provided to;

http://www.cumbria.gov.uk/planning-environment/flooding/floodriskassessment.asp



Flooding History

Troutbeck Bridge has developed around two watercourses; Trout Beck and Bell Beck. Troutbeck Bridge has a long history of flooding, mainly associated with impacts from Bell Beck, which enters culvert upstream of the village behind Brook Street and joins Trout Beck downstream of the Broadfield estate to the south of the A591. The areas in Troutbeck Bridge that are particularly prone to the effects of flooding are Brook Street, Calgarth View and Broadfield, which are all located in close proximity to the Bell Beck culvert.

The following flood events have been recorded in Troutbeck Bridge, with a notable increase in the frequency of flooding from the February 2004 flood event: June 1953, January 1975, February 2004, January 2005, January 2006, October 2008 and November 2009. Local residents also reported a 'near miss' from flooding on 20th November 2015.

Table 1 shows the recorded data from the gauging station located on Trout Beck, situated downstream of Troutbeck Bridge, at a point downstream of where Bell Beck joins Trout Beck. There is currently no gauging station located on Bell Beck.

Flooding Event	Number of Properties Flooded	s the Calgarth the Calgarth Peak o		Time of Recorded Peak on 5 th December
5 th December 2015	7	50.7	2.23m	18:15

Table 1 – Gauged data from the 5th December flood event affecting Troutbeck Bridge

Event background

This section describes the location of the flood incident and identifies the properties that were flooded.

Flooding Incident

Troutbeck Bridge is a village within the South Lakeland District of Cumbria. It is located between two popular tourist towns of Windermere and Ambleside on the A591. In distance, it is approximately 1.3 miles to the north west of Windermere. Figure 1 shows the location of Troutbeck Bridge.

The village consists mainly of residential properties, but there are also commercial properties and a school in the area.

Bell Beck flows through the village mostly in a culverted channel through a built-up, mainly low lying area of residential properties and a school. Bell Beck flows into Trout Beck downstream of the Broadfield estate, which discharges into Lake Windermere downstream of the village. Figure 2 shows the main watercourses around Troutbeck Bridge.




Figure 1 - Location of Troutbeck Bridge




Figure 2 - Location of Watercourses in Troutbeck Bridge

Troutbeck Bridge was affected by flooding on three occasions through December 2015; on the 5th, 6th and 22nd.

On the 5th and 6th December 2015, seven properties are known to have suffered flooding. This flooding can be attributed to a record-breaking rainfall event from Storm Desmond. This led to flooding from Bell Beck, plus flooding from surface water, other local 'ordinary' watercourses and local drainage systems, including the sewage network.

Flooding was primarily associated with the Bell Beck watercourse, with other sources contributing to the flooding impacts experienced. The properties which flooded are in low lying areas and are situated in close proximity to the Bell Beck watercourse. The extent of the flood is illustrated in Figure 3.

Figure 3 shows the approximate extent of the flooding. For this report, the flooded areas have been considered as one area covering Brook Street, Calgarth View, the A591, and Broadfield. These are shown in Figure 4.

Below is a summary of the locations that were affected by flooding:

- The houses on Calgarth View were affected twice in December, on the 5th and 22nd.
- Access issues to Lowther House and 1 Calgarth View.
- Gardens of houses on Broadfield with water entering the cavity of some houses.
- The Lakes School boiler room was affected on 5th December.
- Pedro's (formerly the Sun Hotel) was affected on the 5th of December 2015, resulting in the business being closed.
- Highways drains to the front of the hotel on the A591 were blocked. There were also issues with the culverted ordinary watercourse to the rear.
- There were other occasions throughout the month of December when properties, especially on Calgarth View, would have been affected, but local residents took action to prevent their property from flooding.
- Rough Lane, an access track to the east of Sun Lane across the A592, suffered significant erosion due to flow originating from an ordinary watercourse that flows from How Hill.




Figure 3 - Extent of Flooding in Troutbeck Bridge on 5-6th December 2015




Figure 4 - Identification of Flooded Areas

Current Flood Risk Management & Existing Defences

There are no formal flood defences within Troutbeck Bridge. There is a short length of raised ground upstream of Brook Street adjacent to the Bell Beck culvert inlet, as well as a flow interception trench in the field upstream of Brook Street on the left bank floodplain of Bell Beck. These are shown in Figures 5 and 6.



Figure 5 - Short length of raised ground next to the Bell Beck culvert inlet



Figure 6 - Flow interception trench on the left bank floodplain of Bell Beck

The EA Operations Team inspect the Bell Beck culvert inlet, particularly before and after bad weather, as a 'high priority' site. This is in addition to routine inspections that are carried out as part of the Environment Agency's ongoing role in proactive operational management to reduce flood risk.

In addition to the operational and incident response of the Environment Agency, the following lists the activities carried out to November 2015 on Bell Beck:

- 2004 Bell Beck is designated as a 'main river' and scheduled on a maintenance programme with a CCTV inspection – designation of 'main river' meant that permissive powers transferred from SLDC to the EA.
- 2008 CCTV inspection.
- 2009 Bell Beck maintenance and inlet improvement.
- 2009 Post-November 2009 flood event recovery work.
- 2010 CCTV culvert inspection with maintenance work carried out.
- 2011 Repairs undertaken to the Bell Beck culvert on Brook Street.
- 2011 Riparian land owners made aware of responsibilities with regards to culvert repairs.
- 2011 Funds secured by EA from the Cumbria Community Foundation to contribute to cost of work identified.
- 2014 UU diverts sewer and removes obstruction within Bell Beck culvert, providing additional culvert capacity.

- 2014 Allocation of Local Levy funding to undertake improvements on Bell Beck.
- 2014 Cumbria County Council proposal for culvert overflow to reduce flooding and to rebuild pipe network to improve highway drainage.
- 2015 Twin pipe overflow from Bell Beck culvert installed under A591 downstream of Calgarth View, with improvements to highway drainage.

In 2010, following the November 2009 flooding, Cumbria County Council and the Environment Agency removed stone debris from the Bell Beck culvert. In 2011, the Environment Agency carried out further work to remove masonry debris by digging into the culvert at various locations. By the summer of 2014, United Utilities diverted a sewer that passed through the culvert under Brook Street, removing a significant blockage on Bell Beck (estimated at 30% of the culvert capacity).

In November 2015, Cumbria County Council carried out the installation of a twin pipe overflow from Bell Beck, with support from the Environment Agency. The overflow was designed to operate during high volume flows and during incidents of high water levels, and provides flood relief for the households of Calgarth View Cottages on the A591. This work also included rebuilding the pipe network from the Calgarth View Cottages to further improve the drainage on the A591 and at the Cottages. Cumbria County Council also proposes to carry out work on the school property to facilitate the occasional discharge of flow from the culvert overflow. Cumbria County Council have negotiated with the school and agreed to undertake some work to the school grounds drainage as part of the scheme to reduce flood risk in the area.

Investigation

This section provides details of the rainfall event, the likely causes of flooding and the history of flooding in the area.

This investigation was carried out by the Environment Agency through surveys of the area and data collected from the communities affected, with help from Cumbria County Council and South Lakeland District Council. The Troutbeck Bridge Flood Action Group (FLAG), led by Janet Chapman, have also provided information to Risk Management Authorities (RMA's) following the flood incident at partnership meetings hosted by the Environment Agency. Their input is greatly appreciated.

This report has been complied by CH2M from the data collected by the Environment Agency. CH2M are a global civil engineering consultancy providing a full range of flood management consultancy services in the UK and overseas. CH2M's range of experienced specialists have provided input into understanding this event and producing recommendations for future flood management in Troutbeck Bridge. More details of CH2M's work in the UK is included in Appendix 5.

Rainfall Event

December 2015 was the wettest calendar month on record with much of the northern UK receiving double the average December rainfall. This also followed a particularly wet November, and as such, much of the soil within the Cumbria catchments was already saturated. The 'near miss' flood event reported by the local community on 20th November provides further evidence of this.

From 4th to 7th December there was a period of prolonged, intense rainfall caused by Storm Desmond. Over this period, new 24 hour and 48 hour rainfall records were set for the UK. Both of these were within Cumbria and broke the previous records, also within Cumbria, set during the November 2009 floods.

Record breaking rainfall fell across Cumbria which caused exceptionally high river flows across the county and resulted in widespread flooding. The level of Trout Beck peaked at 2.23m on the Calgarth river level gauge, situated downstream of where Bell Beck joins Trout Beck, at 18:15 on Saturday 5th December. As there is currently no river level gauge on Bell Beck, this provides the best available information relating to the timing of the peak flows on Trout Beck and Bell Beck during the flood event. The location of Calgarth river level gauge is shown in Figure 7.




Figure 7 - Location of Calgarth river level gauge on Trout Beck, Troutbeck Bridge

Table 2 shows the recorded data from the Calgarth gauging station.

Flooding Event	Number of Properties Flooded	Peak flow recorded at the Calgarth Gauge Station (m ³ /s)	Peak level recorded at the Calgarth Gauge Station (m)	Time of Recorded Peak on 5 th December
5 th December 2015	7	50.7	2.23	18:15

Table 2 – Gauged data from Calgarth gauging station on Trout Beck




Figure 8 - Flow recorded on Trout Beck during the December flood event at Calgarth gauging station



Sources of Flooding, Flood Flow Routes and Event Timeline

There were a number of flood flow routes during the event. For investigation purposes, the flooded areas have been covered as one area covering Brook Street, Calgarth View, the A591 and Broadfield as shown in Figure 9.

The details of the flow routes into these areas, the likely causes of flooding and the areas affected are discussed in the 'Likely Causes of Flooding' section. There may also have been other flooding mechanisms that were not identified during this investigation.

Table 3 provides a summary timeline of the key events as the flooding affected Troutbeck Bridge. Further information is hoped to be gathered from the local community during the draft consultation process to inform our understanding of the flood event and update the timeline in Table 3 below.

4 th December	Event
15:22	Flood Alert issued for the Brathay, Rothay & Winster catchments
5 th December	Event
Late morning	Bell Beck overflowing and running down the side of Calgarth Cottages on Brook Street.
15:30	Trash screen on entrance to Bell Beck culvert completely submerged and blocked with rubble.
18:15	Water level in Trout Beck at the Calgarth gauging station peaks.
6 th December	Event
09:00	Water still by-passing the Bell Beck culvert inlet and flowing down Brook Street.

Table 3 - Summary timeline of key events during the Troutbeck Bridge flooding




Figure 9 - Flood Flow Routes in the Brook Street, Calgarth View and Broadfield areas

Likely Causes of Flooding

Flooding from Bell Beck occurred when it overtopped its banks after becoming overwhelmed with high volume flows. At the location of the culvert entrance upstream of Brook Street (see Figure 10), the capacity of the culvert was exceeded by the sheer volume of water flowing down the hillside. Culvert capacity was reduced by large quantities of gravel and stone, mobilised from erosion in the open channel upstream of the culvert, which had been washed downstream into the Bell Beck culvert. Once the culvert capacity had been exceeded in the field upstream of Brook Street, water flowed down Brook Street and through the adjacent fields (Back Acre), towards the Sun Hotel (Pedro's) car park and properties on Calgarth View.



Figure 10 - Bell Beck, looking downstream towards Brook Street (17th December)

There was a contribution to flooding from surface water run-off from the high ground in the upper Bell Beck catchment, which descends towards the A591 at Calgarth View. Local residents reported significant flows down Sun Lane, which is a steep access road that links the A591, from a junction next to the Sun Hotel (Pedro's), to the A592 to the east. Flow down Sun Lane is likely to be from a combination of sources, including surface runoff from the upper catchment and also the highway drainage network not being able to cope with the huge volume of water.

A large contributor of flow down Sun Lane also appears to have originated from an ordinary watercourse, which enters culvert at the top of Rough Lane. Rough Lane is a steep access track to the east of the A592, situated directly opposite the junction of the A592 and Sun Lane. As such, the natural topography and location of Rough Lane and Sun Lane provide a flow route for water towards the A591 and properties in Troutbeck Bridge situated adjacent to the road. The culvert inlet at the top of Rough Lane appears to have been overwhelmed by the volume of water flowing in the ordinary watercourse from Howe Hill, with the resulting flow down Rough Lane causing significant damage to the access track as illustrated in Figure 11. The damage caused to the access track on Rough Lane gives an illustration of the volume and velocity of water flowing down the lane and onwards down Sun Lane towards Troutbeck Bridge during the flood event.



Figure 11 - Damage on Rough Lane, looking downstream towards the A592

Some of the flows from the catchment upstream of the A592 flow across the fields to the north of Sun Lane, and are channelled towards a culvert inlet upstream of the Sun Hotel (Pedro's). The existing culvert pipe has a limited capacity, and evidence of debris around the trash screen post-event suggests that the inlet was partially blocked during the flood event (see Figure 12). Reports from local residents suggest that when this culvert reaches capacity, flow across the fields to the north of Sun Lane is directed in a westerly direction down Sun Lane, and towards Brook Street and Calgarth View.



Figure 12 - Culvert inlet and trash screen upstream of the Sun Inn

Flows from the upper catchments then converged on the A591 at Calgarth View, combining with flows from Bell Beck. Flows then travelled across the A591 towards Broadfield and The Lakes School. It is possible that the Broadfield area was also affected by flooding from surcharging (overflow) of the Bell Beck culvert that passes beneath it. No internal flooding of property was reported on Broadfield, with impacts limited to the flooding of gardens and water entering the cavity underneath some properties.

Local residents at Calgarth View reported that during the flood events in December water was backing up through toilets and utilities in houses, and that raw sewage was visible in the area during the flood events.




Figure 13 - Location of Rough Lane, Sun Lane and culvert inlet at top of Rough Lane

Although the overflow pipes from Bell Beck culvert reportedly worked well during the flood event, resulting in lower water levels in some houses, the overflow is only able to operate to maximum capacity when Bell Beck is 'in culvert'. To maximise performance, the culvert inlet therefore needs to be clear. However, due to the steep nature of the Bell Beck watercourse and catchment, and the amount of material that is mobilised during flood events in the open channel upstream of the culvert inlet, it is inevitable that some blockages may occur, despite the Environment Agency's best efforts to keep the inlet trash screen clear.

Below is a summary of eyewitness comments:

5th December 2015, late morning

At inspection late morning, Bell Beck was overflowing and running down the side of the cottages on Brook Street. Water was also coming over and through the wall at the right hand side of the block of three garages with quite a force.

5th December 2015, 3.30pm

The trash screen on the culvert entrance upstream of Brook Street was completely submerged and blocked with rubble washed downstream. Water was flowing over and through the adjacent field and building up behind the wall at the rear of Back Acre, to approximately 230mm of the top of the wall. From here it was passing through a pedestrian access gate, but debris which had built up on it was restricting some of the flow. From the field it flowed towards the pub car park. Water quickly built up behind the wall adjacent to the garages; it was overtopping the wall as seeping through weak

points in the wall, until part of the wall collapsed causing a large volume of water to flow down the lane, causing further damage to the lane.

6th December 2015

At 9am water was still flowing with some force down the lane and over the wall adjacent to the garages. The drain cover at the corner of Calgarth Cottages, at the bottom of Brook Street where it meets the A591, was completely blocked with a thick layer of gravel. Local residents cleared this blockage, which allowed water flowing down the lane to enter the drain. Sandbags had already been placed at the front corner of Calgarth Cottages to help protect them.

At about lunch time local residents cleared the debris off the trash screen to the Bell Beck culvert. This allowed water to flow back into the culvert and the water that had been flowing down the lane and over the wall by the garage immediately stopped.



Environment Agency Flood Incident Response

Pre-event Warning and Preparation

The Environment Agency's response to the flood event on the 5th and 6th December 2015 started well in advance of the event. This response included provision of sand bags and clearing the Bell Beck culvert inlet ahead of the forecast heavy rainfall.

The Environment Agency and Cumbria County Council are members of the Cumbria Local Resilience Forum. The Cumbria Local Resilience Forum (LRF) is a partnership, made up of all the organisations needed to prepare for and respond to any major emergency in the LRF area. All services and organisations worked together prior to and during the flooding to ensure that the best possible preparations and plans were in place.

The Environment Agency issued a Flood Alert for the Rivers Brathay, Rothay and Winster catchments on Friday 4th December at 15:22. A Flood Alert provides advance notice of possible flooding to low lying land and roads, and also acts as an early notification that river levels are expected to rise and that the Environment Agency are monitoring the situation closely. There are currently no Flood Warning Areas for Troutbeck Bridge, so during the December flood event the Environment Agency updated the Flood Alert daily with relevant information. Further details of the Flood Alert issued can be found in Appendix 4.

Post-event Repairs and Maintenance

Following the flood event, the Environment Agency removed approximately 30 tonnes of gravel from the Bell Beck culvert as part of emergency recovery works. Following this, CCTV survey was undertaken to identify further remaining material within the culvert, which was subsequently removed in June 2016. Following the removal of this material, a further detailed CCTV survey of the Bell Beck culvert was undertaken to fully assess the condition of the culvert. The Environment Agency and their contractors are currently reviewing the CCTV survey to determine whether any repairs to the Bell Beck culvert are required. The Environment Agency will also be undertaking further repairs this summer to the Bell Beck culvert inlet, which will include repairing the damaged headwall structure and installing a new trash screen. The 'bed checks' upstream of the culvert inlet, which are designed to manage the channel gradient of the Bell Beck into the culvert, will also be repaired.

The viability of creating a 'gravel trap' to intercept material upstream of the Bell Beck culvert inlet will also be appraised. Due to the steep gradient of the Bell Beck watercourse, it may not be technically feasible to install a gravel trap in this location, however this will be assessed to determine whether it is a viable solution.

On-going Maintenance Activities

The Environment Agency maintains flood risk management structures and sections of river channel where maintenance actively reduces the risk of flooding to people and property. Activities we undertake are summarised below:

- We deliver targeted maintenance on river channels where the activity is beneficial to the reduction in flood risk. This could include:
 - o Weed Control
 - Grass Control
 - Vegetation Management
 - Invasive Non-Native Species Control
 - Gravel Removal, when justified through investigation and survey

Recommended Actions

The following table details recommended actions for various organisations and members of the public to consider using the Cumbria Floods Partnership's 5 Themes: Resilience, Upstream Management, Strengthening Defences, Maintenance and Water Level Management Boards (WLMBs). Some of these recommendations may have already been carried out or are ongoing.

Cumbria Flood Partnership Theme	Action by	Recommended Action	Timescale
Resilience	Cumbria Local Resilience Forum*	Review and update plans to enable homes and business to be better prepared for flooding and reduce the impacts of flooding. For example, review of evacuation procedures / emergency response.	2016
Resilience	Local Community and Environment Agency	Work with the Troutbeck Bridge Flood Action Group to complete an emergency plan for Winter 2016. Continue to work with all communities to establish a network of Action Groups to share learning and best practice.	2016
Resilience	Residents and South Lakeland District Council	Implement flood resilience measures within flooded properties to reduce the impacts of future flooding. South Lakeland District Council is administering the Flood Recovery and Resilience Grants of up to £5000 per property to help people better protect their homes. A further £2000 top up grant can also be applied for from the Cumbria Flood Recovery Fund.	Closing date for grant applications is end of December 2016
Resilience	South Lakeland District Council, Cumbria County Council and Environment Agency	Review Local Development Plans and Strategic Flood Risk Assessment to reflect current understanding of flooding.	2016
Resilience	Cumbria County Council, United Utilities, Environment Agency and Electricity North West.	Review the resilience of critical transport, utility and power supply infrastructure in relation to flood risk.	2016
Upstream Management	Cumbria Floods Partnership (CFP)	The CFP action plan will consider natural flood management options to reduce flood risk across the catchment. This may also include land use changes and/or flood storage.	Summer 2016
Maintenance	Environment Agency, United Utilities and Cumbria County Council	Carry out inspections and repairs to assets which may have been damaged during the flood event. In particular, undertake repairs to the damaged Bell Beck culvert inlet and remove deposited material from the Bell Beck culvert.	2016

Cumbria Flood Partnership Theme	Action by	Recommended Action	Timescale
Maintenance	Environment Agency	Review the gravel and channel maintenance programme within the catchment in response to the flooding event of 2015.	2016-2017
Maintenance	Environment Agency	A new Environment Agency system is being developed to make it easier for communities to understand what maintenance work is being carried out in their area. Improvements will show exactly when, where and what maintenance is being planned each year. Make sure that communities understand how they can access information on planned maintenance at: https://www.gov.uk/government/publications/river-andcoastal-maintenance-programme	2017
Strengthening Defences	Cumbria County Council, South Lakeland District Council and United Utilities	Review the performance of the existing drainage and sewerage systems during the event to better understand where improvements are required.	2016-2017
Strengthening Defences	Environment Agency in partnership with Cumbria County Council and South Lakeland District Council	Undertake an appraisal of possible flood risk management options to improve the existing Standard of Protection in Troutbeck Bridge. Defence options to be appraised include; replacement of the Bell Beck culvert, flow routing measures to direct flow away from properties, upstream storage and raised defences such as raised walls.	2016-2017

Table 4: Recommended actions for consideration

^{*} The Cumbria Local Resilience Forum includes emergency services, local authorities, Cumbria County Council, Environment Agency, Maritime Coastguard Agency and health agencies along with voluntary and private agencies. Under the Civil Contingencies Act (2004) every part of the United Kingdom is required to establish a resilience forum.

Next Steps

The Cumbria Floods Partnership has brought together a wide range of community representatives and stakeholders from a variety of sectors to plan and take action to reduce flood risk. The Cumbria Floods Partnership, led by the Environment Agency, has produced a 25 year flood action plan for the Cumbrian catchments worst affected by the December 2015 flooding. The Cumbria Flood Action Plan, as well as a series of community action plans, are available online at:

https://www.gov.uk/government/publications/cumbria-flood-action-plan

The plan considers options to reduce flood risk across the whole length of a river catchment including upstream land management, strengthening flood defences, reviewing maintenance of banks and channels, considering water level management boards and increasing property resilience. The Cumbria Floods Partnership structure below details how these 5 themes are being delivered in the Flood Action Plans which were published on 30th June 2016.

The Cumbria Floods Partnership was set up by Flood Minister Rory Stewart MP following December's floods, and includes all of Cumbria's RMAs. They are working alongside the existing 'Cumbria Strategic Partnership', which was formed as part of the Flood and Water Management Act 2010 and comprises of the County's RMAs, including the Environment Agency, Cumbria County Council, Local Authorities and United Utilities. Both partnerships are working with communities, businesses, and relevant stakeholders to understand and reduce flood risk across Cumbria.

Figure 14 helps to demonstrate how the two partnerships are working together.




Figure 14: Cumbria Flood Partnership and Cumbria Strategic Partnership

Appendices

Appendix 1: Glossary

AEP Annual Exceedance Probability

AOD Above Ordnance Datum

CCC Cumbria County Council

EA Environment Agency

FLAG Flood Action Group

FWD Floodline Warnings Direct

LLFA Lead Local Flood Authority

LRF Local Resilience Forum

MSfWG Making Space for Water Group

RMA Risk Management Authority

SLDC South Lakeland District Council

UU United Utilities

Appendix 2: Summary of Relevant Legislation and Flood Risk Management Authorities

The table below summarises the relevant Risk Management Authority and details the various local source of flooding that they will take a lead on.

Flood Source	Environment Agency	Lead Local Flood Authority	District Council	Water Company	Highway Authority
RIVERS		-			
Main river					
Ordinary					
watercourse					
SURFACE					
RUNOFF					
Surface					
water					
Surface					
water on the					
highway					
OTHER					
Sewer					
flooding					
The sea					
Groundwater					
Reservoirs					

The following information provides a summary of each Risk Management Authority's roles and responsibilities in relation to flood reporting and investigation.

<u>Government</u> – DEFRA develop national policies to form the basis of the Environment Agency's and the LLFA's work relating to flood risk.

<u>Environment Agency</u> has a strategic overview of all sources of flooding and coastal erosion as defined in the Act. As part of its role concerning flood investigations this requires providing evidence and advice to support other Risk Management Authorities (RMA's). The EA also collates and reviews assessments, maps, and plans for local flood risk management (normally undertaken by LLFA).

<u>Lead Local Flood Authorities (LLFAs)</u> – Cumbria County Council is the LLFA for Cumbria under the Flood & Water Management Act 2010. Part of their role requires them to investigate significant local flooding incidents and publish the results of such investigations. LLFAs have a duty to determine which RMA has relevant powers to investigate flood incidents to help understand how they happened, and whether those authorities have, or intend to, exercise their powers. LLFAs work in partnership with communities and flood RMA's to maximise knowledge of flood risk to all involved. This function is carried out at CCC by the Development Management Team.

<u>District and Borough Councils</u> – These organisations perform a significant amount of work relating to flood risk management including providing advice to communities and gathering information on flooding. These organisations are classed as RMA's.

<u>Water and Sewerage Companies</u> manage the risk of flooding to water supply and sewerage facilities and the risk to others from the failure of their infrastructure. They make sure their systems have the appropriate level of resilience to flooding and where frequent and severe flooding occurs they are required to address this through their capital investment plans. It should also be noted that following the Transfer of Private Sewers Regulations 2011 water and sewerage companies are responsible for a larger number of sewers than prior to the regulation. These organisations are classed as RMA's

<u>Highway Authorities</u> have the lead responsibility for providing and managing highway drainage and certain roadside ditches that they have created under the Highways Act 1980. The owners of land adjoining a highway also have a common-law duty to maintain ditches to prevent them causing a nuisance to road users. These organisations are classed as RMA's

Flood risk in Cumbria is managed through the Making Space for Water process, which involves the cooperation and regular meeting of the Environment Agency, United Utilities, District/Borough Councils and CCC's Highway and LFRM Teams to develop processes and schemes to minimise flood risk. The MSfWGs meet approximately 4 times per year to cooperate and work together to improve the flood risk in the vulnerable areas identified in this report by completing the recommended actions. CCC as LLFA has a responsibility to oversee the delivery of these actions.

Where minor works or quick win schemes can be identified, these will be prioritised and subject to available funding and resources will be carried out as soon as possible. Any major works requiring capital investment will be considered through the Environment Agency's Medium Term Plan process or a partners own capital investment process.

Flood Action Groups are usually formed by local residents who wish to work together to resolve flooding in their area. The FAGs are often supported by either CCC or the EA and provide a useful mechanism for residents to forward information to the MSfWG.

Appendix 3: Links to Other Information on Flooding

Sign up for Flood Warnings

https://www.gov.uk/sign-up-for-flood-warnings

Environment Agency - Prepare your property for flooding; a guide for householders and small businesses to prepare for floods

https://www.gov.uk/government/publications/prepare-your-property-for-flooding

Environment Agency – What to do before, during and after a flood: Practical advice on what to do to protect you and your property

https://www.gov.uk/government/publications/flooding-what-to-do-before-during-andafter-a-flood

Environment Agency - Living on the Edge: A guide of the rights and responsibilities of riverside occupiers

https://www.gov.uk/government/publications/riverside-ownership-rights-andresponsibilities

Flood and Water Management Act 2010:

http://www.legislation.gov.uk/ukpga/2010/29/contents

Water Resources Act 1991:

http://www.legislation.gov.uk/all?title=water%20resources%20act

Land Drainage Act:

http://www.legislation.gov.uk/all?title=land%20drainage%20act

Appendix 4: Flood Warnings and Alerts

011WAFBR - Rivers Brathay, Rothay and Winster.

Alert issued on Friday 04/12/2015 at 15:22 Alert removed on Tuesday 06/01/2016 at 10:48

Customers in Flood Alert area registered on FWD: 98

Contacts (landline, mobile, email etc) in Flood Alert area registered on FWD: 303

Successful contacts: 267 Unsuccessful contacts: 36

Alert Message:

A Flood Alert has been issued by the Environment Agency for the Rivers Brathay, Rothay and Winster. Flooding is possible for Rivers Brathay, Rothay and Winster. Low lying land and roads will be affected first. Be prepared to protect yourself, family, pets and property.

Heavy and persistent rainfall along with strong South-Westerly winds are forecast to continue this evening (Friday 04/12/2015) through until Sunday (06/12/2015). With the ground already saturated the river and lake levels are expected to rise further and we may see some significant impacts. Newby Bridge Sluices remain open (opened 9th November). The forecast is likely to result in Flood Warnings being issued on Saturday (05/12/2015). We advise that you keep an eye on the situation by listening to weather forecasts, checking our web pages or calling Floodline. We are continuing to monitor the situation and have workers on site operating defences and clearing blockages where required.

Appendix 5: CH2M Hill UK Projects and Flood Risk Management brochure



CH2MHILL.









We partner with your industry

- Municipal Water, Wastewater, and Water Supply
- · Aviation, Ports, Transit, and Rail
- Nuclear Decontamination and Decommissioning
- Chemical Manufacturing
- Environmental Remediation and Compliance Management
- Environmental Industrial Systems
- Commercial Nuclear
- Oil and Gas
- Electronics and Advanced Technologies
- Manufacturing
- Life Sciences
- · Communications Infrastructure
- Security Systems

Employee-owned CH2M HILL is one of the world's leading consulting, design, design-build, operations, and programme management companies serving government, civil, industrial and energy clients, employing over 28,000 people worldwide. Our work is concentrated in the areas of water, transportation, environmental, energy, facilities and resources.

Having operated in the UK for over 20 years, we acquired Halcrow in 2011 and continue to base our European headquarters in London, now employing over 3,300 people in the UK. CH2M HILL is working on some of the most iconic infrastructure programmes including High Speed 2, Thames Tideway Tunnels, the decommissioning of Dounreay and was one of the leading partners in CLM, Delivery Partner to the ODA for the London 2012 Olympic & Paralympic Games.

We serve as a single point of contact and responsibility, managing your project through planning, financing, permitting, design, construction, and operations. We use technology transfer and leverage established relationships with local firms to deliver industrial and enterprise management solutions throughout the United Kingdom.

CH2M HILL is an active member of Business in the Community and the Employee Ownership Association.

© 2013 CH2M HILL COR031913002602DEN

Urban Programmes

Key endorsements:

"From the outset of the project, the Olympic Park has set new standards in sustainability, including delivery of lightweight venues, recycling or reuse of waste materials, using concrete with a high recycled content and delivering materials by rail or water. We have achieved new standards for a project of this size and scale and have raised the bar for the industry."

- John Armitt, ODA Chairman

"The ODA did a fantastic job in delivering the Olympic venues and infrastructure on time and within budget. They did our nation proud."

 Margaret Hodge MP, Chair of the Public Accounts Select Committee



London 2012 Olympic and Paralympic Games CH2M HILL was one of the three first constituting the international consortium CLM, the Delivery Partner to the Olympic Delivery Authority (ODA). CLM oversaw the design and construction of the nine venues across the 500-acre Olympic Park for the London 2012 Olympic and Paralympic Games. CH2M HILL provided the consortium and ODA with global engineering, construction and programme management expertise.

Completed one year ahead of the games, the programme was delivered at an impressive £1Bn under the baseline budget of £7.2Bn with notably zero construction fatalities, the first of such records of any modern Olympics.



Water

Thames Tideway Tunnel and Lee Tunnel

CH2M HILL is the programme manager for the London Tideway Tunnels Programme, one of the biggest and most historic public works initiatives in London's history. With the Rivers Lee and Thames currently overflowing approximately 50-60 times annually, the London Tideway Tunnels Programme looks to reduce overflows to three or less per year.

The programme will see the construction of the Lee Tunnel and the Thames Tideway Tunnel and aims to greatly improve the river quality and reduce the environmental impact of sewerage overflows. Both tunnels will be more than seven metres wide, running beneath a vast network of existing tunnels, including six Underground lines and utilities. The programme includes constructing numerous collection and diversion facilities, a large high-head underground pumping station, and a major upgrade at Beckton sewage treatment works. Ultimately, CH2M HILL will manage over 300 work packages. So far, CH2M HILL have delivered £700M of savings on a £4.1Bn budget and carried out exemplary stakeholder relations across 14 London Boroughs.

© 2013 CH2M HILL COR031913002602DEN

Transport

Crossrail

As Europe's largest engineering project, Crossrail will connect 37 stations, including Heathrow airport and Maidenhead in the west with Canary Wharf, Abbey Wood and Shenfield in the east—reducing journey times across London while delivering extensive economic benefits.

The Transcend team, which includes CH2M HILL, AECOM and The Nichols Group, was appointed as the programme partner to work alongside Crossrail to oversee the construction of a 21 kilometre-long tunnel beneath central London, build eight new stations and integrate Crossrail with London's existing transport systems. Additionally, the team is responsible for programme controls, encompassing the functions of scope, cost and schedule control, as well as risk and value management.

When Crossrail opens in 2018, the £14.8Bn rail link will boost London's rail-based network capacity by ten percent—transporting 200 million passengers annually, bolster the capital's position as a world-leading financial center, and significantly reduce journey times across the city.



High Speed 2 (HS2)



HS2 will be the UK's new high speed rail network and is being designed and built to resolve impending capacity issues for both passengers and freight on existing routes, particularly the West Coast Main Line.

The network will provide enhanced infrastructure links between London and the West Midlands (Phase One), as well as the Channel Tunnel, expanding in future to connect Manchester, Leeds and the North with Birmingham, the south of England and Heathrow Airport (Phase Two).

CH2M HILL is development partner with HS2 Ltd and is leading the development of the next phase of engineering, design and environmental work on the London to the West Midlands line. The 80 strong team, working alongside HS2 Ltd, largely consists of project management and engineering specialists from the UK. The team project manage the professional services companies who are carrying out the design, environmental and land referencing work for the London to West Midlands line. CH2M HILL's expertise ensures that the work is fully integrated and delivered to the required quality.

On appointing CH2M HILL, HS2 Ltd's Chief Executive Alison Munro said: "The appointment means that we will have world class project managers and technical experts working alongside us to deliver the design, engineering and environmental work necessary for the hybrid bill. They will bring, in particular, their highly regarded experience of working on HS1 and Crossrail, two major UK infrastructure projects that have direct relevance to our work."

We provide services for your success

- Programme and Project Management
- Site Selection
- Infrastructure Planning
- Economic Development
- Energy Management and Planning
- Information Systems
- Master Planning
- Licensing and Permitting
- Management Consulting
- Project Financing
- Project Development
- Architecture and Programming
- LEED and BREEAM Facility Certification
- Civil, Structural, Mechanical, and Electrical Engineering

© 2013 CH2M HILL COR031913002602DEN



Water Resources-Ecosystem Management Services

Flood Risk Management

CH2M is a world leader in flood risk management, providing integrated and sustainable solutions for both the built and natural environment. Our large team of specialists and scientists, who are primarily based in the UK and USA, deliver projects around the world. They are supported by environmental scientists, surveyors, geotechnical engineers, and business planning, finance and contract, and other specialists. Our work includes the full cycle of flood risk mapping and strategic planning; capital works delivery, and operation, maintenance and asset management.

The solutions we develop recognize the effect climate change is increasingly having on the built and natural environment within river catchments and estuaries, and thus our focus is on developing long-term solutions that work with nature and continue to leave a sustainable legacy to protect future generations from the effects of climate change.

A core focus is delivering fully integrated solutions that maximize both direct and indirect benefits for the clients that we serve in WBG, TBG and Strategic Consulting. This means we are linked with several technologies including IWRM, Dams and Levees (Conveyance), Water Resilience, H&H modeling (Software Applications and Integration), Urban Watershed Management; and Coastal Planning and Engineering.

Sub-technologies

The FRM technology group has three key sub-technology areas that we steward, offering several capabilities in each:

Flood mapping and appraisal

- · Watershed-scale flood risk management planning
- Flood hazard modeling/mapping and hydraulic analysis
- · Flood risk management alternatives development and testing
- Risk vulnerability and damage analysis
- · Flood forecasting/warning
- · Flood incident management and exercise

Capital works delivery

- · Program/project management
- · Conceptual, preliminary and final design
- · Contract preparation and administration
- Construction supervision
- Due diligence and other pre-bid assistance

O&M and asset management (AM)

- Asset management
- · Strategic and tactical investment advice
- Disaster recovery

Challenges, Trends, Opportunities

Floods are increasing in frequency around the world and it is forecast that these will only get worse as a result of climate change. As the frequency of floods increases, the tolerance of the public, governments, the private sector, and insurance companies is reducing, prompting action.

A key market differentiator is being able to deliver multiple outcomes to clients through a river basin management approach which links together flood risk management needs with regeneration, recreational, and environmental enhancement opportunities and combines the associated available funding to generate both efficiencies and the financial support necessary for scheme delivery.

To achieve this we need to combine our flood risk management capabilities and technology with our knowledge of what the issues are within the river basins.

Did You Know?

- A review by the Organization for Economic Cooperation and Development on 136 coastal cities found that the estimated damage from sea level rise, storm surge and subsidence for 1 in 100 year flood event in 2070 was estimated at \$35,000 billion.
- In 2070 it is estimated that over 150 million people will live in these 136 coastal cities at risk.
- · River flooding is the most common type of flood event.
- · Floods are the number one natural disaster in the US, and just a few inches of water from a flood can cause tens of thousands of dollars in damage.
- The flooding in Alberta, Canada in 2013 flooding displaced 100,000 people and is estimated to cost \$6 billion.
- According to the House of Commons library, £2.34 billion has been spent on new flood defenses in England alone since 2011.