

# Cumbria Countryside Access

## UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5566	OS Map	96	
Total length	0.5	Grid References	From	332 894
Length unsurfaced	0.5		To	338 892
		Location	Rusland Pool	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	<b>X</b>
	Route with little or no use not likely to require monitoring/management	
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	R & S France	Organization	TRF
Date	08/07/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	10%
	Crushed stone		Mud	
	Rocky	90%	Other	

Condition of surface (rutted, washed out, etc.) Good

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)

Ford can be very deep  
Abandon route rather than divert

Considerations for use and sensitivity re ecological issues, farming issues, other

TRO from Oct 1 to May 31 due to salmon spawning

General description of route, and observations  Good gravel track to and from river, steep climb out of river on south side	Signed from main highway	No
	Signed both ends	
	Access from main Highway	Yes
	Route	Yes
	- through	
	- dead end	
	Fords or water crossings	Yes
Gradient	Yes	
- generally flat		
- generally undulating		
- has steep hills		

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage			
	Approx. width at narrowest		15ft	

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Trampler use? ( motorized scooters for the disabled with off road capability)	Looks practical		Maybe	
	No	Yes		