

# Cumbria Countryside Access

## UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5590	OS Map	97	
Total length	0.56	Grid References	From	442 914
Length unsurfaced	0.56		To	442 909
		Location	Crosthwaite	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	Yes
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	R & S France	Organization	TRF
Date	22/04/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	100%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Good standard crushed stone

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re ecological issues, farming issues, other Used for dog walking

General description of route, and observations  Incorrectly signed as footpath at southern end – path starts 100 yards up UCR  Hedged farm lane	Signed from main highway	No
	Signed both ends	
	Access from main Highway - easy	Yes
	Route - awkward	
	- through	Yes
	- dead end	
	Fords or water crossings	No
Gradient - generally flat		
- generally undulating	Yes	
- has steep hills		

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest			

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	No
	2 wheels	No

Worth evaluating for Tramper use? ( motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe
	No		