

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or	5341- 02	OS Map	97	
BOAT Number	547021	Grid References	From	496 848
Total length	1.14		To	504 840
Length unsurfaced	1.14	Location	Levens Hall, SE off A6	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/managment	
	Route with moderate use requiring some monitoring/managment	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	R & S France	Organization	TRF
Date	22/04/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	80%
	Crushed stone	10%	Mud	10%
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Underlying hard surface with grass and sometimes mud on top

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations Part hedged, part walled lane, potential to be overgrown House at northern end Not suitable for 4x4s	Signed from main highway	Yes
	Signed both ends	Yes
	Access from main - easy	Yes
	Highway - awkward	
	Route - through	Yes
	- dead end	
	Fords or water crossings	
	Gradient - generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	No	Trail bike	Yes
	Carriage	No		
	Approx. width at narrowest	6ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe
	No		