Cumbria Countryside Access

UCR and BOAT Survey Form

	UCR and E	SOAT Survey Fo				
UCR Number and/or	5290	OS Map	97			
BOAT Number		Grid References	From	607 981		
Total length	1.58		То	604 967		
ength unsurfaced	1.58	Location	Cowpe	rthwaite		
CCC Classification	Route with significant use	requiring significant	monitoring	g/managment		
(Tick recommendation)						
	Route with little or no use	not likely to require	monitoring	/ managemen	t	Yes
	Unsuitable route, should n	ot be on MPV susta	inable acc	ess map		
LDNPA classification if	applicable, criteria as above	e, but green become	es light gre	en for dead ei	nds	
Surveyor	R & France	Organization	TRF			
Date	22/04/16	or interest				
		or milerest				
Surface (note % of eac	h type of surface	Tarmac		Grass		
Surface (note % of each type of surface, Describe "other")		Crushed stone	100%	Mud		
		Rocky	10070	Other		
0 1101		-				
Condition of surface (ru	utted, washed out, etc.)	Rather rutted at n	ortnern en	a, with deep p	ouddies	
Apparent sensitivity to	winter/weather conditions					
(river crossing, flooding	g, surface damage, other)		None			
Considerations for use	and sensitivity re					
	•		None			
ecological issues, farm	•		Signed fr	om main high	way	Yes
ecological issues, farm	route, and observations	oor porthorn	Signed fr Signed b	oth ends		No
ecological issues, farm General description of Walled track between f	ing issues, other	near northern	Signed fr Signed b Access fr	oth ends om main - e	asy	
ecological issues, farm General description of Walled track between f	route, and observations	near northern	Signed fr Signed b Access fr Highway	oth ends om main - e - a	asy wkward	No Yes
ecological issues, farm General description of Walled track between f	route, and observations	near northern	Signed fr Signed b Access fr	oth ends om main - e - a - th	asy	No
ecological issues, farm General description of Walled track between f	route, and observations	near northern	Signed fr Signed b Access fr Highway Route	oth ends om main - e - a - th	asy wkward nrough lead end	No Yes
ecological issues, farm General description of Walled track between f	route, and observations	near northern	Signed fr Signed b Access fr Highway Route	oth ends om main - e - a - tl - d	asy wkward nrough lead end	No Yes Yes
ecological issues, farm General description of Walled track between f	route, and observations	near northern	Signed fr Signed b Access fr Highway Route	oth ends om main - e - a - th - d water crossing - generally th - generally th	asy wkward nrough lead end gs lat undulating	No Yes Yes
ecological issues, farm General description of Walled track between f	route, and observations	near northern	Signed fr Signed b Access fr Highway Route	oth ends om main - e - a - th - d water crossing - generally fl	asy wkward nrough lead end gs lat undulating	No Yes Yes
ecological issues, farm General description of Walled track between f	route, and observations	ear northern	Signed fr Signed b Access fr Highway Route	oth ends om main - e - a - th - d water crossing - generally th - generally th	asy wkward nrough lead end gs lat undulating	No Yes Yes
General description of Walled track between fend	route, and observations ields, high grass in middle n	2 wheel drive	Signed fr Signed b Access fr Highway Route Fords or Gradient	oth ends om main - e - a - th - d water crossing - generally fl - generally u - has steep h	asy wkward nrough lead end gs lat undulating	No Yes Yes
General description of Walled track between fend	route, and observations ields, high grass in middle n	2 wheel drive 4 wheel drive	Signed fr Signed b Access fr Highway Route Fords or Gradient	oth ends om main - e - a - th - d water crossing - generally fl - generally u - has steep h	asy wkward nrough lead end gs lat indulating nills	No Yes Yes
General description of Walled track between fend	route, and observations ields, high grass in middle n	2 wheel drive 4 wheel drive Carriage	Signed fr Signed b Access fr Highway Route Fords or Gradient	oth ends om main - e - a - th - d water crossing - generally th - generally u - has steep th Quad Trail bike	asy wkward nrough lead end gs lat indulating nills	No Yes Yes
ecological issues, farm General description of Walled track between fend	route, and observations ields, high grass in middle n	2 wheel drive 4 wheel drive	Signed fr Signed b Access fr Highway Route Fords or Gradient	oth ends om main - e - a - th - d water crossing - generally fl - generally u - has steep h	asy wkward nrough lead end gs lat indulating nills	No Yes Yes
General description of Walled track between fend	route, and observations relds, high grass in middle n	2 wheel drive 4 wheel drive Carriage	Signed fr Signed b Access fr Highway Route Fords or Gradient	oth ends om main - e - a - th - d water crossing - generally th - generally u - has steep th Quad Trail bike	asy wkward nrough lead end gs lat indulating nills	No Yes Yes
General description of Walled track between fend Should normally be passes	route, and observations ields, high grass in middle n ssable by	2 wheel drive 4 wheel drive Carriage	Signed fr Signed b Access fr Highway Route Fords or Gradient	oth ends om main - e - a - th - d water crossing - generally th - generally u - has steep th Quad Trail bike	asy wkward nrough lead end gs lat indulating nills	No Yes Yes
Walled track between fend Should normally be passed to b	route, and observations ields, high grass in middle n ssable by	2 wheel drive 4 wheel drive Carriage	Signed fr Signed b Access fr Highway Route Fords or Gradient	oth ends om main - e - a - th - d water crossing - generally th - generally u - has steep h Quad Trail bike 12 ft	asy wkward nrough lead end gs lat indulating nills	No Yes Yes