

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5304	OS Map	97	
Total length	0.7	Grid References	From	551 974
Length unsurfaced	0.5		To	545 970
		Location	Patton Bridge	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	R & S France	Organization	TRF
Date	13/05/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	100%
	Crushed stone		Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Good

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations Part walled, part open field, tarmac with grass in the middle	Signed from main highway	No
	Signed both ends	No
	Access from main Highway	Yes
	Route	Yes
	Fords or water crossings	
	Gradient	Yes

Should normally be passable by	2 wheel drive	Quad	Yes
	4 wheel drive	Trail bike	Yes
	Carriage		
	Approx. width at narrowest	5ft	

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe
	No		