

# Cumbria Countryside Access

## UCR and BOAT Survey Form

UCR Number and/or BOAT Number	1142	OS Map	85	
Total length	4.77	Grid References	From	377 589
Length unsurfaced	2.28		To	378 459
		Location	Raughtonhead	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	<b>X</b>
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S. Stout	Organization	TRF
Date	16/04/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	100%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.)      Somewhat rutted with grass centre

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)      Will develop deep puddles in wet weather

Considerations for use and sensitivity re ecological issues, farming issues, other      None

General description of route, and observations  Hedged farm type lane. Used by tractors.  Western section is Signed Public Way at both ends, with Bridleway on same sign. Route is not Bridleway North/Eastern section signed Public Way	Signed from main highway	Yes	
	Signed both ends	Yes	
	Access from main Highway	- easy - awkward	Yes
	Route	- through - dead end	Yes
	Fords or water crossings		
	Gradient	- generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	12 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Tramper use? ( motorized scooters for the disabled with off road capability)	Looks practical		Maybe	Yes
	No			