

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	1158	OS Map	85	
Total length	1.375	Grid References	From	418 483
Length unsurfaced	1.3		To	431 483
		Location	Foulbridge	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S. Stout	Organization	TRF
Date	16/04/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac	15%	Grass	
	Crushed stone	85%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Good surface with some puddles, broken tarmac at eastern end

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re ecological issues, farming issues, other
Used regularly by horse stables nearby, plus farm vehicles access fields – proceed slowly

General description of route, and observations Wide, hedged lane, crossing M6	Signed from main highway	No
	Signed both ends	
	Access from main Highway - easy	Yes
	Route - awkward	
	- through	Yes
	- dead end	
	Fords or water crossings	
Gradient - generally flat	Yes	
- generally undulating		
- has steep hills		

Should normally be passable by	2 wheel drive	No	Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	12 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason
4 wheels
2 wheels

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)
Looks practical Yes Maybe
No