

## Cumbria Countryside Access

### UCR and BOAT Survey Form

UCR Number and/or BOAT Number	U2170	OS Map	89
Total length		Grid References	From 078 317 To 078 333
Length unsurfaced		Location	Little Broughton

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S Stout	Organization or interest	TRF
Date	22/10/16		

Surface (note % of each type of surface, Describe "other")	Tarmac	50%	Grass	
	Crushed stone	50%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.)      Good surface with some rutting

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)

None

Considerations for use and sensitivity re ecological issues, farming issues, other

Farmer locks gates at north end

General description of route, and observations  Route runs from the centre of Little Broughton to a cross road at next minor road Section beyond here dead ends at wood. It does not go through to Hennah Hall	Signed from main highway	
	Signed both ends	Yes
	Access from main - easy	Yes
	Highway - awkward	
	Route - through	Yes
	- dead end	
	Fords or water crossings	No
	Gradient - generally flat	Yes
	- generally undulating	
	- has steep hills	

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest		12 ft	

Recommend one way use due to steepness, narrowness, other condition, state reason

4 wheels  
2 wheels

Worth evaluating for Trampler use? ( motorized scooters for the disabled with off road capability)

Looks practical      Yes      Maybe  
No