

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	3147	OS Map	90	
Total length	0.52	Grid References	From	446 296
Length unsurfaced	0.52		To	440 294
		Location	Greystoke	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	X
	Route with little or no use not likely to require monitoring/ management	
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S Stout	Organization	TRF
Date	13/06/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	Yes
	Crushed stone		Mud	
	Rocky	Yes	Other	

Condition of surface (rutted, washed out, etc.) Rutted and somewhat washed out

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) Prone to flooding in wet weather

Considerations for use and sensitivity re ecological issues, farming issues, other Close to houses at eastern end

General description of route, and observations Narrow, hedged route, overgrown and with washed out sections	Signed from main highway	No
	Signed both ends	
	Access from main Highway	- easy - awkward
	Route	- through - dead end
	Fords or water crossings	
	Gradient	- generally flat - generally undulating - has steep hills
		Yes

Should normally be passable by	2 wheel drive	No	Quad	Yes
	4 wheel drive	No	Trail bike	Yes
	Carriage	No		
	Approx. width at narrowest	6 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical		Maybe
	No	No	