

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	2234	OS Map	90	
Total length	0.53	Grid References	From	295 217
Length unsurfaced	4.9		To	312 232
		Location	Dale Bottom	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S Stout	Organization	TRF
Date	13/16/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	100%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Good

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)

Hairpins from Dale Bottom washes out slightly and are very tight, solid surface all along length, however

Considerations for use and sensitivity re ecological issues, farming issues, other

General description of route, and observations	Signed from main highway	No
	Signed both ends	
	Access from main Highway - easy	Yes
	Route - through - dead end	Yes
	Fords or water crossings	
	Gradient - generally flat	
	- generally undulating	Yes
- has steep hills	Yes	

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	12 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason

4 wheels

2 wheels

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)

Looks practical Yes Maybe

No