## **Cumbria Countryside Access**

## **UCR and BOAT Survey Form**

	OCK and B	OAT Survey Fo	OHIII			
UCR Number and/or		OS Map	89			
BOAT Number		Grid References	From	237 368		
Total length	200m		То	236 369		
Length unsurfaced	200m	Location	Ruthwaite	e		
CCC Classification	Route with significant use re	equiring significant	monitorin	g/managment	t	
(Tick recommendation)	Route with moderate use requiring some monitoring/managment					
	Route with little or no use not likely to require monitoring/ management					X
	Unsuitable route, should no	t be on MPV sustai	inable acc	ess map		
I DNPA classification if	applicable, criteria as above	hut areen hecome	se liaht are	en for dead e	ande	
				cirioi dedd e	1103	
Surveyor	S.Stout	Organization	TRF			
Date	01/11/16	or interest				
Surface (note % of eac	h type of surface,	Tarmac		Grass	50%	
Describe "other")		Crushed stone	50%	Mud		
		Rocky		Other		
Condition of surface (ru	itted, washed out letc.)	Some ruts				
Condition of Canaco (10	ittou, wadnou out, oto.)	_ Como rato				
Apparent sensitivity to	winter/weather conditions					
	g, surface damage, other)	None				
Considerations for use ecological issues, farmi	•	Passes close to h	ouse in th	e hamlet		
General description of route, and observations grassy lane to access fields and hamlet from tarmac road			Signed from main highway			No
			Signed both ends Access from main - easy			Yes
grassy rane to access n	Toau	Highway		easy wkward	162	
			Route		hrough	Yes
			riodio		dead end	
			Fords or	water crossing		
			- generally f		Yes	
				y undulating		
				- has steep	hills	
Should normally be pas	ssable by	2 wheel drive	No	Quad	Yes	
	<u> </u>	4 wheel drive	Yes	Trail bike	Yes	1
		Carriage	Yes			-
		Approx. width at r	narrowest			
Recommend one way I			4 wheels			
Recommend one way use due to steepness, narrowness, other condition, state reason				2 wheels		
						]
	ramper use? ( motorized	Looks practical	No	Maybe		
scooters for the disable	d with off road capability)	No				