

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or		OS Map	91	
BOAT Number	323012	Grid References	From	610 393
Total length	1.7		To	627 393
Length unsurfaced	1.7	Location	Gamblesby	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/managment	
	Route with moderate use requiring some monitoring/managment	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S Stout	Organization	LARA / TRF
Date	17/11/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	90%
	Crushed stone	10%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Slightly rutted

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations Walled grass track over hardcore Leaving the route onto A686 (fast traffic) needs great care	Signed from main highway	No
	Signed both ends	
	Access from main Highway	No (at A686)
	Route	Yes
	Fords or water crossings	
	Gradient - generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	12 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical		Maybe	Yes
	No			