

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or		OS Map	91	
BOAT Number	349041	Grid References	From	728 217
Total length	1.1 km		To	721 208
Length unsurfaced	1.1km	Location	Murton	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/managment	
	Route with moderate use requiring some monitoring/managment	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S Pighills	Organization	TRF
Date	10/01/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	25%
	Crushed stone	75%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc), some minor wash out at southern end

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)	None
---	------

Considerations for use and sensitivity re ecological issues, farming issues, other	Watch out for donkeys off middle section Passes through grazing fields
--	---

General description of route, and observations Good condition track with 2 gates	Signed from main highway	Yes
	Signed both ends	Yes
	Access from main - easy	Yes
	Highway - awkward	
	Route - through	Yes
	- dead end	
	Fords or water crossings	
Gradient - generally flat		
- generally undulating	Yes	
- has steep hills		

Should normally be passable by	2 wheel drive	Yes	Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	10ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe
	No		