

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	3091	OS Map	91	
Total length	2.169	Grid References	From	591 385
Length unsurfaced	1.587		To	598 373
		Location	Broadmeadows	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S Stout	Organization	TRF
Date	09/12/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	80%
	Crushed stone	20%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Slightly rutted from farm use, hard packed for SE 30%, then soft grass and back to hard packed at NW end

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) Can be muddy in wet weather

Considerations for use and sensitivity re ecological issues, farming issues, other Pass farm slowly. Caravan site at junction with A686

General description of route, and observations Walled track through farm land (turns right at gateway)	Signed from main highway	No
	Signed both ends	
	Access from main Highway - easy	Yes
	Route - through - dead end	Yes
	Fords or water crossings	
	Gradient - generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	12 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical	Maybe	Yes
	No		